

TEST TERRAIR SHEETS

OCEANEARING R&D

6/22/09

Original substrate has failed not epoxy product.

**Original substrate on back
OF SAMPLE** →



NOT SANDED BETWEEN COATS

TO LONG OF TIME BETWEEN COATS TO APPLY SECOND COAT

EXRAYED

Standard packaging tape was put on back of failed material and was pulled off showing powdered debris not allowing bonding to concrete.



Minster

